TROUBLESHOOTING GUIDE





TABLE OF CONTENTS

THERMOPLASTIC COATINGS

Booth Recovery Equipment	4
leaning and Phosphating	5
Cured Film Appearance	7
Cured Film Physical Properties	10
Oven Problems	11
Powder Application	12
Powder Feeding	14

THERMOPLASTIC COATINGS

Thermoplastic materials are one of many types of coatings known for their recyclability and versatility of application.

We stand behind our products, even when things don't go as planned. From cleaning and phosphating to the final appearance of the cured film, we are here to help you solve your problems with proven solutions.

BOOTH AND RECOVERY EQUIPMENT

Poor powder containment

CAUSE	SOLUTIONS
	1a. Ensure correct "seasoning" of filters or cartridges
	1b. Check filter pulse operation
Primary collector filter media blinding	1c. Clean or replace filter media
	1d. Ensure clean, dry compressed air
	1e. Control humidity
	2a. Ensure correct "seasoning" of filters or cartridges
2. Final filters blinded or restricted	2b. Repair primary filter leaks
	2c. Repair or clean final filters
3. Improper gun placement	3. Reposition guns
4. Cross drafts	4. Eliminate cross drafts
5. Inadequate booth draw	Maintain proper airflow (typical range is 80-150 fpm depending on booth size)
6. Too many guns, excessive powder output	6. Reduce number of guns or powder output

Contamination in reclaim powder

CAUSE	SOLUTIONS
1. Inadequate equipment cleaning	1. Clean pear supplier recommendations
2. Sieve problems	2. Repair or replace screen
3. Falling dirt or debris	3. Clean conveyor, hangers, or other overhead equipment
4. Loose debris on substrate	4. Ensure clean substrate
5. Airborne contaminant	5a. Isolate spray booth area 5b. Eliminate source of contamination

Poor transfer efficiency or powder utilization

CAUSE	SOLUTIONS
1. Air turbulence	Isolate spray booth area Locate source and eliminate
2. Excessive booth draw	Maintain proper airflow (typical range is 80-150 fpm depending on booth size) Consult equipment supplier
3. Poor line density	3. Improve line density

CLEANING AND PHOSPHATING

Inadequate Cleaning

CAUSE	SOLUTIONS
1. Improper temperature	1. Adjust temperature to specs
2. Low solution concentration	2. Adjust cleaner concentration
3. Poor exposure to cleaner	3a. Improve part presentation 3b. Clean Spray nozzles 3c. Adjust spray pressure
4. Short dwell time in cleaner	4. Extend part exposure time
5. Wrong cleaner for soils	5. Change cleaner or metal
6. Depleted chemicals	6. Recharge chemicals

Low phosphate coating weight (mg./sq.ft.)

CAUSE	SOLUTIONS
1. pH out of range	1. Adjust pH
2. Inadequate cleaning of substrate	2. See A: Inadequate cleaning
3. Low phosphate concentration	3. Increase concentration
4. Inadequate exposure	4a. Reduce line speed 4b. Clean plugged spray nozzles

Cleaning and/or phosphate solutions foaming

CAUSE	SOLUTIONS
1. Solution temperature too low	1. Raise temperature
	2a. Clean plugged spray nozzles
2. Spray pressures too high	2b. Use recommended pressures
	2c. Use correct nozzles
	3a. Eliminate leaks in pump packing
3. Pump picking up air	3b. Adjust solution level
	3c. Mesh screens clogged up.
4. Cleaner concentration too high	4. Reduce concentration
5. Type of cleaning or phosphate solution	5. Use low foaming spray solutions

Streaked or spotted phosphate, white patterns

CAUSE	SOLUTIONS
	1a. Trace cause of deposit patterns
	1b. Add halo misting rinse
1. Poor rinsing	1c. Increase rinse overflow
1. Poor rinsing	1d. Clean spray nozzles
	1e. Adjust pressure
	1f. Check rinse water solids level
2. Poor cleaning	2. See A: Inadequate cleaning
3. Phosphate % too high or low	3. Adjust phosphate concentration
4. High phosphate temperature	4. Reduce phosphate temperature

Flash rusting of parts

CAUSE	SOLUTIONS
	1a. Adjust phosphate temperature
1. Phosphate coating weight too low	1b. Extend part exposure time
	1c. Increase phosphate concentration
	2a. Reduce temperatures
2. Drying between pretreatment stages	2b. Apply water mist on parts between stages
	2c. Increase line speed
	3a. Extend exposure time
	3b. Eliminate carry-over
3. Poor rinsing	3c. Check spray pressure/nozzles
	3d. Check rinse water tanks/overflow
4. Low pH pickling of substrate	4.Increase pH to recommended level
	5a. Prevent line stoppage
5. Line stoppage	5b. Apply water mist on parts between stages
	5c. Run at lower temperatures
	6a. Increase dry-off oven temperature
C. Dw. off to a class	6b. Increase dry-off oven air movement
6. Dry-off too slow	6c. Ensure parts are draining well
	6d. Increase final rinse temperature

FLOWED FILM APPEARANCE

Voids, craters or pinholes

CAUSE	SOLUTIONS
1. Inadequate cleaning of substrate	1. See cleaning and phosphating Trouble A
2. Airborne contaminants (silicone, oils, powders, etc.)	2. Locate source and eliminate
3. Oil in compressed air supply	3. Ensure clean, dry air
4.Incompatible powders	4a. Proper equipment cleaning 4b. Verify with your powder supplier

Outgassing or blistering

CAUSE	SOLUTIONS
1. Castings, other porous substrate	1. De-gas at or above cure temperature
2. Low film thickness	2. Increase film thickness
3. Ash from burn-off oven	3. Ensure using clean hooks & parts
4. Plating	4. Consult with plater
	5a. Remove paint
5. Liquid paint under powder	5b. Use appropriate liquid paint
	5c. De-gas at or above cure temperature

High orange peel or roughness

CAUSE	SOLUTIONS
1. Improper thickness	1. Adjust film thickness (thicker)
2. Back ionization	2. See Powder Application
3. Substrate profile	3a. Increase film thickness 3b. Modify substrate
4. Slow heat-up rate	4a. Increase cure temperature 4b. Preheat substrate
5. Powder stored at or exposed to elevated temperature	5a. Replace powder 5b. Store powder at or below recommended temperature

Part surface contamination

CAUSE	SOLUTIONS
1. Contamination from oven interior	1a. Eliminate source of contamination 1b. Clean entire oven interior 1c. Clean or replace filtration 1d. Clean oven air handling equipment
2. Falling dirt or debris	2. Clean conveyor, hangers, or other overhead equipment
3. Inadequate cleaning	3. See Cleaning and Phosphating
4. Contamination from plant air	4a. Isolate spray booth areas 4b. Eliminate source of contamination
5. Compressed air	5. Ensure clean, dry air
6. Sieve	6. Repair or replace screen

Inconsistent film thickness

CAUSE	SOLUTIONS
Manual spray technique	1a. Choose alternative gun tips to improve powder cloud diffusion
	1b. adjust spray technique
2. Poor part ground	2. Ensure all ground contacts are not more than 1 megohm resistance in coating zone (as required by NFPA)
	3a. Reposition gun
3. Improper gun placement	3b. Increase gun distance to part and apply final dusting layer
4. Plugged guns or defective spray equipment	4. See Powder Application
5. Reciprocators not synchronized	5a. adjust line speed
	5b. Adjust reciprocator stroke sequence
6. Excessive directional air flow in booth	6. See Booth & Recovery Equipment

Picture Framing

CAUSE	SOLUTIONS
1. Excessive film thickness	1. Reduce film thickness
2. Poor part grounding	2. Ensure ground contacts are not more than 1 1 megohm resistance in coating zone (as required by NFPA)
3. High gun Kv	3. Reduce gun Kv

Off-color or yellowing

CAUSE	SOLUTIONS
	1a. Reduce dwell time or temperature
1. Overbaking	1b. Increase line speed
1. Overbaking	1c. Calibrate oven
	1d.Check burner locations/baffles to eliminate hot spots
2. Line stoppages	2a. Eliminate line stoppages or reduce oven temperature stoppages
	2b. Leave gaps to provide for scheduled line stoppages
3. Heat-sensitive powder type	3. Consult with Protech Group
4. Inadequate oven exhaust	4a. Increase oven exhaust rate
	4b. Reduce line loading

Low gloss

CAUSE	SOLUTIONS
1. Overbaking	1. Reduce dwell time or temperature
2. Incompatible powder in system	2. Clean application equipment before changing powder
3. Widespread microscopic pinholes	3. See trouble A: Voids, craters, or pinholes

High gloss

CAUSE	SOLUTIONS
1. Undercured coating	1. Increase cure time or temperature
2. Slow heat-up rate	2a. Increase temperature 2b. Preheat substrate

Coating pulls away from corners or welds

CAUSE	SOLUTIONS
1. Inadequate metal pretreatment	1. See Cleaning & Phosphating
	2a. Grit blast weld
2. Contamination on surface of weld	2b. Increase chemical cleaning of weld
	2c. Change weld flux
	3a. Increase time or temperature in dry-off oven
	3b. Fixture parts to improving draining
3. Moisture retention in recess	3c. blow off water w/compressed air
	3d. Mask or plug recesses
	3e. Redesign part or drill holes for drainage

FLOWED FILM PHYSICAL PROPERTIES

Poor adhesion

CAUSE	SOLUTIONS
1. Inadequate substrate heat	1. Increase oven time or temperature
2. Inadequate cleaning of substrate	2. See Cleaning & Phosphating
3. Change in substrate or soils	3. Modify metal preparation for new metal or soils
4. Phosphate coating too heavy	4a. Reduce phosphate temperature
	4b. Reduce phosphate concentration
5. Pretreatment process contamination	5. Find and eliminate sources of contamination (silicone, oils, etc.)

Poor chemical resistance

CAUSE	SOLUTIONS
1. Inadequate substrate heat	1. 5Increase oven time or temperature
2. Improper chemistry for application	2. Consult powder supplier
3. Voids in coating	3a. Increase coating thickness 3b. See Cured Film Appearance

Poor corrosion

CAUSE	SOLUTIONS
1. Inadequate substrate heat	1. Increase oven time or temperature
2. Inadequate metal pretreatment	2. See Cleaning & Phosphating
3. Voids in coating	3a. Increase coating thickness 3b. See Cured Film Appearance
4. Inadequate edge coverage	4a. Eliminate sharp edges 4b. Increase film thickness
5. Improper chemistry for application	5. Consult with Protech Group

Poor impact or flexibility

CAUSE	SOLUTIONS
1. Inadequate substrate heat	1. Increase oven time or temperature
2. Inadequate metal pretreatment	2. See cleaning & Phosphating
3. Low film thickness	3. Increase Coating and thickness

OVEN PROBLEMS

Temperature does not equal set point

CAUSE	SOLUTIONS
1. Thermocouple/heat source fault	1. Check circuitry for continuity
2. Controller out of calibration	2. Calibrate or replace
3. Thermocouple/capillary failure	3. Replace thermocouple/capillary
4. Positive or negative pressure	4. Check surrounding area pressure
5. Air seal, relief, exhaust failure	5. Check air handling equipment
6. Air turbulence	6. Perform an air survey
7. Low gas pressure	7. Check inlet gas pressure
8. Exceeding mass loading capacity	8a. Reduce product mass loading 8b. Modify or replace oven
9. Fuel/air ratio incorrect	9. Adjust to specifications
10. Placement of temperature sensor	10. Relocate sensor in oven

Pilot will not light

CAUSE	SOLUTIONS
1. Main gas valve closed	1. Open main gas valve
2. Safety controls open	2. Trace wiring, correct control
3. Gas pressure incorrect	3. Check manufacturer's specs
4. Ignition transformer fault	4a. Check igniter, clean, or replace 4b. Check ignition cable
4. Igilittoii ttalisioilliei laut	4c Check ignition transformer
5. Improper pilot setting	5. Check pilot orifice setting
6. Purge cycle not complete	6a. Complete cycle
	6b.Check purge timer

Main burner will not light

CAUSE	SOLUTIONS
1. Main valve closed	1. Open main valve
2. Manifold valve/circuits open	2. Trace wiring, look for fault
3. Pilot valve will no open	3. Inspect and replace if needed
4. Faulty signal from flame system	4. Monitor signal, adjust/replace
5. Incorrect gas pressure setting	5. Adjust to specifications
6. Full control motor failure	6. Repair and/or replace motor
7. Faulty air flow switch	7. Check switch settings/performance
8. Hi-temp lock-out activated	8. Correct cause of high temperature

Coil won't energize (electric)

CAUSE	SOLUTIONS
1. Wiring fault	1. Check all wires and connections
2. Fuse/breaker fault	2. Correct cause of fuse fault
3. Low air flow through coil	3a. Check air flow sensor 3b. Check for adequate air flow

POWDER APPLICATION

Thin film

CAUSE	SOLUTIONS
1. Poor part ground	Ensure all ground contacts are not more than 1 megohm resistance in coating zone (as required by NFPA)
2. Poor charging	2a. Increase Kv.2b. Clean or replace electrodes, cables, etc., as needed2c. Decrease powder delivery rate
3. High humidity in ambient air	3. Control environment
4. Excessive fines	4. Add virgin powder
5. Low deposition rate	5a. Increase powder delivery air 5b. reduce line speed

Poor penetration in Faraday areas

CAUSE	SOLUTIONS
1. Voltage not optimized	1. Adjust Kv
2. Powder delivery rate not optimized	2. Adjust delivery rate
3. Poor part ground	3. Ensure all ground contacts are not more than 1 megohm resistance in coating zone (as required by NFPA)
4. Poor gun replacement	4. Adjust gun position
5. Poor powder spray pattern	5. Consider alternate gun tips
6. Poor part presentation	6. Improve part presentation
7. Wrong type of gun nozzle	7. Change gun nozzle type

Back ionization

CAUSE	SOLUTIONS
1. Gun voltage too high	1. Reduce Kv
2. Gun is too close to part	2. Increase gun to part distance
3. Poor part ground	3. Ensure all ground contacts are not more than 1 megohm resistance in coating zone (as required by NFPA)
4. Excessive powder build-up	4. Apply thinner film
5. Insulating first coat (recoating)	5a. Reduce kv, ensure good grounding 5b. Pre-heat part before coating

Powder surging or spitting

CAUSE	SOLUTIONS
1. Powder delivery rate not optimized	1. Optimize powder delivery rate
2. Improper hose diameter	2. Use smaller diameter hose
3. Poor hopper fluidization	3. Optimize fluiding pressure
4. Improper air pressure or air volume	4. Optimize air pressure
5. Kinked or fattened hoses	5a. Eliminate sharp bends, kinks, or obstructions in or on hoses 5b. Replace if permanently deformed
6. Clogged/worn parts, tubes or hoses	6. Clean or replace worn parts, tubes or hoses, etc., as needed
7. Powder level too low	7. Ensure powder level is above bottom of pick-up tubes
8. Moisture in compressed air	8. Ensure clean, dry air
9. Excessive powder fines	9. Add virgin powder

Poor spray pattern

CAUSE	SOLUTIONS
1. Powder delivery rate not optimized	1. Optimized powder delivery rate
2. Blockage	2. Clean hoses,pumps, etc.
3. Worn parts	3. Replace worn parts

POWDER FEED

Powder drifting out of hopper

CAUSE	SOLUTIONS
1. Fluidizing air too high	1. Reduce air pressure
2. Hopper too full	2. Reduce powder level
3. Poor hopper ventilation	3a. Remove obstructions in hopper vent 3b. Check vent assist device
4. Excessive fines	4. Add virgin powder

No air percolating through powder in fluidizer

CAUSE	SOLUTIONS
1. No air pressure	Check for crimped hoses Adjust air pressure
2. Plugged fluidizer membrane	2. Replace membrane

Air channels through powder during fluidization

CAUSE	SOLUTIONS
1. Powder level too low	1. Increase powder level
2. Deals as majet massides	2a. Sieve powder and fluidize
2. Pack or moist powder	2b. Ensure compressed air is clean and dry
	3a. Remove membrane obstructions
3. Membrane conditions	3b. Replace plugged or broken membrane
	3c. Ensure membrane seal is intact
4. Excessive fines	4. Add virgin powder
5. High humidity in ambient air	5. Control environment

Restricted powder hoses and pumps

CAUSE	SOLUTIONS
1. Normal buildup	1. Clean or replace hoses or parts
	2a. Reduce air pressure(s)
	2b. Ensure compressed air is clean and dry
	2c. Clean hoses and parts
2. Impact fusion	2d. Replace worn parts
	2e. Eliminate exposure to heat
	2f.Eliminate sharp bends, kinks, or obstructions in or on hoses
	2g. Add virgin powder to increase particle size
3. Kinked or flattened hoses	3a. Eliminate sharp bends, kinks or obstructions in or on horses
	3b. Replace if permanently deformed

Insufficient powder feed

CAUSE	SOLUTIONS
1. Powder level too low	1. Increase powder level
2. Powder not fluidizing	2. Refer to trouble: Powder drifting out of hopper, No air percolating through powder in fluidizer, and Air channels through powder during fluidization
3. Obstruction of powder delivery	3a. Clean feed tubes, pumps, hoses and guns 3b. Eliminate kinked od flattened hoses
4. Excessive hose length	4a. Reduce hose length 4b. Increase air pressure
5. Low delivery air	5. Increase air pressure
6. Worn pump parts	6a. Replace worn parts 6b. Reduce air pressure
7. Kinked or flattened hoses	7. See trouble related to Restricted powder hoses and pumps

ASK AN EXPERT

Our coating experts can help you simplify the process, save you time and Our coating experts can help you streamline the process, saving you time and money by providing the right coating advice for your product or project.





americas@protechpowder.com

EUROPE, MIDDLE EAST & AFRICA (EMEA)

emea@protechpowder.com



ASIA-PACIFIC asia@protechpowder.com