TROUBLESHOOTING GUIDE





TABLE OF CONTENTS

THERMOSET POWDER COATINGS

Booth Recovery Equipment	. 6
Cleaning and Phosphating	. 7
Cured Film Appearance	. 8
Cured Film Physical Properties	. 11
Oven Problems	13
Powder Application	14
Powder Feeding	16

THERMOSET POWDER COATINGS

Thermoset materials are used for the majority of powder coating processes because they can provide both a durable and decorative surface layer.

We stand behind our products, even when things don't go as planned. From cleaning and phosphating to the final appearance of the cured film, we are here to help you solve your problems with proven solutions.

BOOTH AND RECOVERY EQUIPMENT

Poor powder containment

CAUSE	SOLUTIONS
	1a. Ensure correct "seasoning" of filters or cartridges
	1b. Check filter pulse operation
Primary collector filter media blinding	1c. Clean or replace filter media
	1d. Ensure clean, dry compressed air
	1e. Control humidity
	2a. Ensure correct "seasoning" of filters or cartridges
2. Final filters blinded or restricted	2b. Repair primary filter leaks
	2c. Repair or clean final filters
3. Improper gun placement	3. Reposition guns
4. Cross drafts	4. Eliminate cross drafts
5. Inadequate booth draw	Maintain proper airflow (typical range is 80-150 fpm depending on booth size)
6. Too many guns, excessive powder output	6. Reduce number of guns or powder output

Contamination in reclaim powder

CAUSE	SOLUTIONS
1. Inadequate equipment cleaning	1. Clean pear supplier recommendations
2. Sieve problems	2. Repair or replace screen
3. Falling dirt or debris	3. Clean conveyor, hangers, or other overhead equipment
4. Loose debris on substrate	4. Ensure clean substrate
5. Airborne contaminant	5a. Isolate spray booth area5b. Eliminate source of contamination

Poor transfer efficiency or powder utilization

CAUSE	SOLUTIONS
1. Air turbulence	1a. Isolate spray booth area 1b. Locate source and eliminate
2. Excessive booth draw	2a. Maintain proper airflow (typical range is 80-150 fpm depending on booth size)2b. Consult equipment supplier
3. Poor line density	3. Improve line density

CLEANING AND PHOSPHATING

Inadequate Cleaning

CAUSE	SOLUTIONS
1. Improper temperature	1. Adjust temperature to specs
2. Low solution concentration	2. Adjust cleaner concentration
	3a. Improve part presentation
3. Poor exposure to cleaner	3b. Clean Spray nozzles
	3c. Adjust spray pressure
4. Short dwell time in cleaner	4. Extend part exposure time
5. Wrong cleaner for soils	5. Change cleaner or metal
6. Depleted chemicals	6. Recharge chemicals

Low phosphate coating weight (mg./sq.ft.)

CAUSE	SOLUTIONS
1. pH out of range	1. Adjust pH
2. Inadequate cleaning of substrate	2. See A: Inadequate cleaning
3. Low phosphate concentration	3. Increase concentration
4. Inadequate exposure	4a. Reduce line speed 4b. Clean plugged spray nozzles

Cleaning and/or phosphate solutions foaming

CAUSE	SOLUTIONS	
1. Solution temperature too low	1. Raise temperature	
	2a. Clean plugged spray nozzles	
2. Spray pressures too high	2b. Use recommended pressures	
	2c. Use correct nozzles	
	3a. Eliminate leaks in pump packing	
3. Pump picking up air	3b. Adjust solution level	
	3c. Mesh screens clogged up.	
4. Cleaner concentration too high	4. Reduce concentration	
5. Type of cleaning or phosphate solution	5. Use low foaming spray solutions	

Streaked or spotted phosphate, white patterns

CAUSE	SOLUTIONS
	1a. Trace cause of deposit patterns
	1b. Add halo misting rinse
1 Decument	1c. Increase rinse overflow
1. Poor rinsing	1d. Clean spray nozzles
	1e. Adjust pressure
	1f. Check rinse water solids level
2. Poor cleaning	2. See A: Inadequate cleaning
3. Phosphate % too high or low	3. Adjust phosphate concentration
4. High phosphate temperature	4. Reduce phosphate temperature

Flash rusting of parts

SOLUTIONS
1a. Adjust phosphate temperature
1b. Extend part exposure time
1c. Increase phosphate concentration
2a. Reduce temperatures
2b. Apply water mist on parts between stages
2c. Increase line speed
3a. Extend exposure time
3b. Eliminate carry-over
3c. Check spray pressure/nozzles
3d. Check rinse water tanks/overflow
4. Increase pH to recommended level
5a. Prevent line stoppage
5b. Apply water mist on parts between stages
5c. Run at lower temperatures
6a. Increase dry-off oven temperature
6b. Increase dry-off oven air movement
6c. Ensure parts are draining well
6d. Increase final rinse temperature

CURED FILM APPEARANCE

Voids, craters or pinholes

CAUSE	SOLUTIONS
1. Inadequate cleaning of substrate	1. See cleaning and phosphating Trouble A
2. Airborne contaminants (silicone, oils, powders, etc.)	2. Locate source and eliminate
3. Oil in compressed air supply	3. Ensure clean, dry air
4. Incompatible powders	4a. Proper equipment cleaning 4b. Verify with your powder supplier

Outgassing or blistering

SOLUTIONS
1. De-gas at or above cure temperature
2. Reduce film thickness
3. Ensure using clean hooks & parts
4. Consult with plater
5a. Remove paint
5b. Use appropriate liquid paint
5c. De-gas at or above cure temperature

High orange peel or roughness

SOLUTIONS
1. Adjust film thickness
2. See Powder Application
3a. Increase film thickness 3b. Modify substrate
Increase cure temperature Ab. Preheat substrate
5a. Replace powder 5b. Store powder at or below recommended temperature

Part surface contamination

CAUSE	SOLUTIONS
	1a. Eliminate source of contamination
1. Contamination from oven interior	1b. Clean entire oven interior
1. Containing for Home over interior	1c. Clean or replace filtration
	1d. Clean oven air handling equipment
2. Falling dirt or debris	2. Clean conveyor, hangers, or other overhead equipment
3. Inadequate cleaning	3. See Cleaning and Phosphating
	4a. Isolate spray booth areas
4. Contamination from plant air	4b. Eliminate source of contamination
5. Compressed air	5. Ensure clean, dry air
6. Sieve	6. Repair or replace screen

Inconsistent film thickness

CAUSE	SOLUTIONS
1. Manual spray technique	1a. Choose alternative gun tips to improve powder cloud diffusion 1b. adjust spray technique
2. Poor part ground	Ensure all ground contacts are not more than 1 megohm resistance in coating zone (as required by NFPA)
3. Improper gun placement	3a. Reposition gun 3b. Increase gun distance to part and apply final dusting layer
4. Plugged guns or defective spray equipment	4. See Powder Application
5. Reciprocators not synchronized	5a. adjust line speed 5b. Adjust reciprocator stroke sequence
6. Excessive directional air flow in booth	6. See Booth & Recovery Equipment

Picture Framing

CAUSE	SOLUTIONS
1. Excessive film thickness	1. Reduce film thickness
2. Poor part grounding	Ensure ground contacts are not more than 1 1 megohm resistance in coating zone (as required by NFPA)
3. High gun Kv	3. Reduce gun Kv

Off-color or yellowing

CAUSE	SOLUTIONS
	1a. Reduce cure time or temperature
1. Overshalding	1b. Increase line speed
1. Overbaking	1c. Calibrate oven
	1d.Check burner locations/baffles to eliminate hot spots
2. Line stoppages	2a. Eliminate line stoppages or reduce oven temperature stoppages
	2b. Leave gaps to provide for scheduled line stoppages
3. Heat-sensitive powder type	3. Consult with Protech Group
4. Inadequate oven exhaust	4a. Increase oven exhaust rate
	4b. Reduce line loading

Low gloss

CAUSE	SOLUTIONS
1. Overbaking	1. Reduce cure time or temperature
2. Incompatible powder in system	2. Clean application equipment before changing powder
3. Widespread microscopic pinholes	3. See trouble A: Voids, craters, or pinholes

High gloss

CAUSE	SOLUTIONS
1. Undercured coating	1. Increase cure time or temperature
2. Slow heat-up rate	2a. Increase cure temperature 2b. Preheat substrate

Coating pulls away from corners or welds

CAUSE	SOLUTIONS
Inadequate metal pretreatment	1. See Cleaning & Phosphating
	2a. Grit blast weld
2. Contamination on surface of weld	2b. Increase chemical cleaning of weld
	2c. Change weld flux
	3a. Increase time or temperature in dry-off oven
	3b. Fixture parts to improving draining
3. Moisture retention in recess	3c. blow off water w/compressed air
	3d. Mask or plug recesses
	3e. Redesign part or drill holes for drainage

CURED FILM PHYSICAL PROPERTIES

Poor adhesion

SOLUTIONS
1. Increase oven time or temperature
2. See Cleaning & Phosphating
3. Modify metal preparation for new metal or soils
4a. Reduce phosphate temperature 4b. Reduce phosphate concentration
5. Find and eliminate sources of contamination (silicone, oils, etc.)

Poor chemical resistance

CAUSE	SOLUTIONS
1. 55Undercured coating	1. 5Increase oven time or temperature
2. Improper chemistry for application	2. Consult powder supplier
3. Voids in coating	3a. Increase coating thickness 3b. See Cured Film Appearance

Poor corrosion resistance

CAUSE	SOLUTIONS
1. Undercured coating	1. Increase oven time or temperature
2. Inadequate metal pretreatment	2. See Cleaning & Phosphating
3. Voids in coating	3a. Increase coating thickness 3b. See Cured Film Appearance
4. Inadequate edge coverage	4a. Eliminate sharp edges 4b. Increase film thickness
5. Improper chemistry for application	5. Consult with Protech Group

Poor impact or flexibility

CAUSE	SOLUTIONS
1. Undercured coating	1. Increase oven time or temperature
2. Inadequate metal pretreatment	2. See cleaning & Phosphating
3. Excessive film thickness	3. Reduce Coating and thickness

Low hardness or abrasion resistance

CAUSE	SOLUTIONS
1. Undercured coating	1. Increase oven time or temperature
2. Improper Chemistry for application	2. Consult with Protech Group



Temperature does not equal set point

CAUSE	SOLUTIONS
1. Thermocouple/heat source fault	1. Check circuitry for continuity
2. Controller out of calibration	2. Calibrate or replace
3. Thermocouple/capillary failure	3. Replace thermocouple/capillary
4. Positive or negative pressure	4. Check surrounding area pressure
5. Air seal, relief, exhaust failure	5. Check air handling equipment
6. Air turbulence	6. Perform an air survey
7. Low gas pressure	7. Check inlet gas pressure
8. Exceeding mass loading capacity	8a. Reduce product mass loading 8b. Modify or replace oven
9. Fuel/air ratio incorrect	9. Adjust to specifications
10. Placement of temperature sensor	10. Relocate sensor in oven

Pilot will not light

CAUSE	SOLUTIONS
1. Main gas valve closed	1. Open main gas valve
2. Safety controls open	2. Trace wiring, correct control
3. Gas pressure incorrect	3. Check manufacturer's specs
4. Ignition transformer fault	4a. Check igniter, clean, or replace
	4b. Check ignition cable
	4c Check ignition transformer
5. Improper pilot setting	5. Check pilot orifice setting
6. Purge cycle not complete	6a. Complete cycle
	6b.Check purge timer

Main burner will not light

CAUSE	SOLUTIONS
1. Main valve closed	1. Open main valve
2. Manifold valve/circuits open	2. Trace wiring, look for fault
3. Pilot valve will no open	3. Inspect and replace if needed
4. Faulty signal from flame system	4. Monitor signal, adjust/replace
5. Incorrect gas pressure setting	5. Adjust to specifications
6. Full control motor failure	6. Repair and/or replace motor
7. Faulty air flow switch	7. Check switch settings/performance
8. Hi-temp lock-out activated	8. Correct cause of high temperature

Coil won't energize (electric)

CAUSE	SOLUTIONS
1. Wiring fault	1. Check all wires and connections
2. Fuse/breaker fault	2. Correct cause of fuse fault
3. Low air flow through coil	3a. Check air flow sensor 3b. Check for adequate air flow

POWDER APPLICATION

Thin film

CAUSE	SOLUTIONS
1. Poor part ground	Ensure all ground contacts are not more than 1 megohm resistance in coating zone (as required by NFPA)
2. Poor charging	2a. Increase Kv. 2b. Clean or replace electrodes, cables, etc., as needed
z. Fooi charging	2c. Decrease powder delivery rate
3. High humidity in ambient air	3. Control environment
4. Excessive fines	4. Add virgin powder
5. Low deposition rate	5a. Increase powder delivery air
•	5b. reduce line speed

Poor penetration in Faraday areas

CAUSE	SOLUTIONS
1. Voltage not optimized	1. Adjust Kv
2. Powder delivery rate not optimized	2. Adjust delivery rate
3. Poor part ground	3. Ensure all ground contacts are not more than 1 megohm resistance in coating zone (as required by NFPA)
4. Poor gun replacement	4. Adjust gun position
5. Poor powder spray pattern	5. Consider alternate gun tips
6. Poor part presentation	6. Improve part presentation
7. Wrong type of gun nozzle	7. Change gun nozzle type

Back ionization

CAUSE	SOLUTIONS
1. Gun voltage too high	1. Reduce Kv
2. Gun is too close to part	2. Increase gun to part distance
3. Poor part ground	3. Ensure all ground contacts are not more than 1 megohm resistance in coating zone (as required by NFPA)
4. Excessive powder build-up	4. Apply thinner film
5. Insulating first coat (recoating)	5a. Reduce kv, ensure good grounding5b. Pre-heat part before coating

Powder surging or spitting

CAUSE	SOLUTIONS
1. Powder delivery rate not optimized	1. Optimize powder delivery rate
2. Improper hose diameter	2. Use smaller diameter hose
3. Poor hopper fluidization	3. Optimize fluiding pressure
4. Improper air pressure or air volume	4. Optimize air pressure
5. Kinked or fattened hoses	5a. Eliminate sharp bends, kinks, or obstructions in or on hoses5b. Replace if permanently deformed
6. Clogged/worn parts, tubes or hoses	6. Clean or replace worn parts, tubes or hoses, etc., as needed
7. Powder level too low	7. Ensure powder level is above bottom of pick-up tubes
8. Moisture in compressed air	8. Ensure clean, dry air
9. Excessive powder fines	9. Add virgin powder

Poor spray pattern

CAUSE	SOLUTIONS
1. Powder delivery rate not optimized	1. Optimized powder delivery rate
2. Blockage	2. Clean hoses,pumps, etc.
3. Worn parts	3. Replace worn parts

POWDER FEED

Powder drifting out of hopper

CAUSE	SOLUTIONS
1. Fluidizing air too high	1. Reduce air pressure
2. Hopper too full	2. Reduce powder level
3. Poor hopper ventilation	3a. Remove obstructions in hopper vent 3b. Check vent assist device
4. Excessive fines	4. Add virgin powder

No air percolating through powder in fluidizer

CAUSE	SOLUTIONS
1. No air pressure	1a. Check for crimped hoses 1b. Adjust air pressure
2. Plugged fluidizer membrane	2. Replace membrane

Air channels through powder during fluidization

CAUSE	SOLUTIONS
1. Powder level too low	1. Increase powder level
2 Park an majet navydan	2a. Sieve powder and fluidize
2. Pack or moist powder	2b. Ensure compressed air is clean and dry
3. Membrane conditions	3a. Remove membrane obstructions
	3b. Replace plugged or broken membrane
	3c. Ensure membrane seal is intact
4. Excessive fines	4. Add virgin powder
5. High humidity in ambient air	5. Control environment

Restricted powder hoses and pumps

CAUSE	SOLUTIONS
1. Normal buildup	1. Clean or replace hoses or parts
	2a. Reduce air pressure(s)
	2b. Ensure compressed air is clean and dry
	2c. Clean hoses and parts
2. Impact fusion	2d. Replace worn parts
	2e. Eliminate exposure to heat
	2f.Eliminate sharp bends, kinks, or obstructions in or on hoses
	2g. Add virgin powder to increase particle size
3. Kinked or flattened hoses	3a. Eliminate sharp bends, kinks or obstructions in or on horses
	3b. Replace if permanently deformed

Insufficient powder feed

CAUSE	SOLUTIONS
1. Powder level too low	1. Increase powder level
2. Powder not fluidizing	2. Refer to trouble: Powder drifting out of hopper, No air percolating through powder in fluidizer, and Air channels through powder during fluidization
3. Obstruction of powder delivery	3a. Clean feed tubes, pumps, hoses and guns 3b. Eliminate kinked od flattened hoses
4. Excessive hose length	4a. Reduce hose length 4b. Increase air pressure
5. Low delivery air	5. Increase air pressure
6. Worn pump parts	6a. Replace worn parts 6b. Reduce air pressure
7. Kinked or flattened hoses	7. See trouble related to Restricted powder hoses and pumps

ASK AN EXPERT

Our coating experts can help you simplify the process, save you time and Our coating experts can help you streamline the process, saving you time and money by providing the right coating advice for your product or project.





americas@protechpowder.com

EUROPE, MIDDLE EAST & AFRICA (EMEA)

emea@protechpowder.com



ASIA-PACIFIC asia@protechpowder.com