CARE & MAINTENANCE





Protech Group thermoplastic coatings

are the ideal choice to protect and enhance your products. To ensure the life of your asset is maximized, a simple and regular maintenance program should be implemented.

Refer to your Technical Data Sheet for more specific information

STORING



Thermoplastic coatings can be formulated differently. Poor storage conditions will affect them in different ways despite having the same storage and condition period. Variations in storage temperatures may lead to a reaction within the container that will ultimately make the thermoplastic difficult to apply.

Here are a few tips to follow during the storing process. Under these conditions, our thermoplastic coatings will have a shelf life of at least 12 months.

- During transport, avoid over-stacking containers leading trailer roof if you take care of logistics.
- -For storage, stockpile containers in an area with

an ambient temperature of 27°C (80°F) at no more than 55% relative humidity.

- Prior to the application, set a few containers in the application room for a few hours before production if the temperature differential between the application room and the warehouse varie de manière significative (± 20°F - ± 10°C).

CLEANING



The frequency of recommended cleaning will first vary depending on the environment and end-use: level of moisture and condensation or airborne contaminant level (interior) or environment and surroundings such as cities, rural, industrial or coastal environment (exterior). Indoor and outdoor usage both have circumstances that command more frequent cleaning.

Cleaning your coated surface is as easy as one, two and three:

- Carefully remove any loose surface deposits with a wet sponge by gently rubbing.
- 2. Clean by gently rubbing the surface with a soft brush (non-abrasive) and a dilute solution of a mild detergent, e.g. pH-neutral liquid hand or dishwashing detergent in warm water to remove dust, salt and other deposits. For stubborn stains, use only recommended solvents on the affected area, e.g. Isopropyl alcohol (IPA) or methylated spirits and rinse off with clean water. Do not use other aggressive solvents.
- 3. Rinse the surfaces with clean fresh water after cleaning to remove all residues.

SECTION 3

MAINTAINING

Some of the influencing factors that can affect the life of Protech Group thermoplastic coatings include:

- -Ultra violet light;
- Levels of atmospheric pollution including salts, dirt, grime that can accumulate over time;
- Winds carrying air borne debris that can cause erosive wear of the coating e.g. sand causing abrasion;
- -Change in environmental circumstances e.g. if rural became industrial;

Use the following table to identify the recommended minimum maintenance schedule for your product or project:

| Environment | Conditions | CORROSIVE ZONE | EXAMPLE ENVIRONMENTS | Recommended Minimum Cleaning |
|-------------|------------|---------------------------|-------------------------|---------------------------------|
| EXTERIOR | Mild | Low | Light | Every 12months |
| | | Medium | Arid Urban Area | Every 6 months |
| | SEVERE | High | Sea Shore (calm) | Every 6 months |
| | | Very High (Industrial) | Heavy Industrial | Every 3 months |
| | | Very High (Marine) | Sea Short (rough) | Every 3 months |
| | TROPICAL | Tropical | Humid | Every 3 months |
| INTERIOR | GENERAL | Very Low | Dry | Every 12 months |
| | | Low | Minor Condensation | Every 12 months |
| | MODERATE | Medium | High Moisture | Every 6 months |
| | | High | Significant | Every 3 months |
| | | | Contamination | |



PROTECTING



Clean in mild conditions

Clean coated surfaces when the surface temperatures are below 25°C (77°F)

O DO NOT

Use aggressive solvents

Do not use turpentine, white spirits, thinners, citrusbased cleaners or other aggressive solvents on coating.

Remove unwanted paint & sealants

Ensure all paint splatters or excess sealant are immediately removed before they dry.

Use recommended solvents for stubborn stains only

Use only Isopropyl alcohol (IPA) or methylated spirits and rinse off with clean fresh water.

Rub powder coated surfaces excessively

Do not rub powder coated surfaces excessively, especially metallic finishes.

Neglect recommended care and maintenance schedules

To comply with Protech Group thermoplastic coating warranties the recommended care and maintenance schedules must be adhered to.

ASKING AN EXPERT

Our coating experts can help simplify the process, saving you time and money by providing the right coating advice for your product or project.





americas@protechpowder.com

EUROPE, MIDDLE EAST & AFRICA (EMEA)

emea@protechpowder.com



ASIA-PACIFIC asia@protechpowder.com